# **Geoprobe® PVC Well Materials & Accessories**

#### **PVC** Riser

- -(32320) PVC RISER 2.0 X 60 in.
- -(17405) PVC RISER 1.5 X 60 in.
- -(12876) PVC RISER 1.0 X 60 in.
- -(11747) PVC RISER .75 X 60 in.
- -(GW2050) PVC RISER .50 X 60 in.



#### **PVC Screens .1 Slot**

-(36200) PVC PIPE 2.0 in. .01 SLOT 60 in. -(17404) PVC PIPP 1.5 in. .01 SLOT 60 in. -(12875) PVC PIPE 1.0 in. .01 SLOT 60 in. -(17474) PVC PIPE .75 in. .01 SLOT 60 in. -(17599) PVC PIPE .50 in. .01 SLOT 60 in.





Geoprobe® 8040DT turning 8.25 in. HSA

#### **PVC Bottom Plugs**

- -(32456) 2.0 in. Bottom Plug -(17407) 1.5 in. Bottom Plug
- -(12881) 1.0 in. Bottom Plug
- -(12385) .75 in. Bottom Plug
- -(GW2056) .50 in. Bottom Plug



## **PVC Locking Caps**

- -(WP1720) Locking Cap 2.0 in. -(WP1715) Locking Cap 1.5 in. -(WP1710) Locking Cap 1.0 in. -(WP1775) Locking Cap .75 in.
- -(WP1750) Locking Cap .75 in. -(WP1750) Locking Cap .50 in.



# **Well Development & Sampling Tools**

- -(29149) 2.0 in. Well Development Tool
- -(34558) 1.5 in. Well Development Tool
- -(35364) 1.0 in. Well Development Tool
- -(GW4210) TUBING CHECK VALVE 3/8 in. OD TUBING
- -(GW4220) TUBING CHECK VALVE 1/2 in. OD TUBING
- -(GW4230) TUBING CHECK VALVE 5/8 in. OD TUBING
- -(GW4240) TUBING CHECK VALVE 1/4 in. OD TUBING
- -(GW41) SS Mini Bailer 20 ml.
- -(37893) Tubing Check Valve 3/8 in (Use w/ LW Center Rods



## **Well Accessories**

- -(AT91) Granular Bentonite #16 50 lb bag
- -(AT92) Powdered Bentonite 200 mesh 50 lb bag
- -(AT95) Silica Sand 20/40 mesh 75lb pail
- -(GW2000) GW Level Meter 100 ft. x 7/16 in.

#### **Well Covers**

- -(WP1741) Well Cover 4 in. Cast Aluminum x 12 in. Long PVC Skirt
- -(WP1771) Well Cover 7 in. Cast Iron x 10 in. Long Aluminum Skirt

